

WEB-PLC V1.96 - Known Bugs

Component: WEB-PLC - Editor (5 matches)

Ticket	Summary	Description	Workaround
#5	Elements can be moved out of the diagram	In the WEB-PLC editor elements can be moved outside the visible area of diagram. They are still there, but cannot be edited any more.	
#715	Timer switching with wrong interval if Clk output port is negated	If the Clk output port of a timer unit is negated, the timer will ignore the given interval and switch the port at maximum speed.	
#1003	Editor catches the delete key even if a dialog is open	The WEB-PLC editor catches the delete key and thus deletes the selected element even if a dialog is open and the key is pressed inside this dialog.	
#1005	Counter units overflow port only set for one cycle	The Overflow port of the counter unit is only set for one PLC cycle in case of an overflow. The documentation states that it will be set until the counter value changes the next time.	
#1063	Diagram cannot be saved when edited with zoom	When the diagram has been edited while the zoom feature of the web browser was used, it may not be possible to save the diagram. The error message "JSON: This is a floating point number." will be shown. The problem has been observed in Microsoft Internet Explorer 11.	

Component: WEB-PLC - General (4 matches)

Ticket	Summary	Description	Workaround
#709	OpenVPN server with port number >32767 does not work	The OpenVPN does not work with servers that use a port number higher than 32767. The message "OpenVPN Driver: Options error: Bad port number: <port number>" is logged.	
#792	Floating point values are cut on home page	On the home page when floating point values from an I/O driver are displayed, the decimal places of these values are cut.	
#837	OpenVPN server with port number >32767 still does not work	The OpenVPN does not work with servers that use a port number higher than 32767. The message "OpenVPN Driver: Options error: Bad port number: <port number>" is logged. This issue was already described in ticket #709 , but the fix for this ticket was not effective.	
#1025	Problems with 32 GB SDHC cards	The SDHC card driver has problems with 32 GB cards. The size is calculated wrongly, which may lead to access failures.	

Component: WEB-PLC - Run Time System (1 match)

Ticket	Summary	Description	Workaround
#1289	Digital outputs on com.tom M-BUS cannot switch faster than once every second	The digital outputs of com.tom M-BUS devices (EXT03) cannot switch faster than once every second. If you try to switch them faster than this, they will not switch at all. If you try to switch them only slightly slower they may switch or not.	

Component: WEB-PLC - Settings Website (2 matches)

Ticket	Summary	Description	Workaround
#54	Fields on settings page not validated	The fields on the settings page are not validated. Any invalid input is accepted.	
#1053	Dialogs have fields marked erroneous initially	When input fields in a dialog are marked red due to illegal input values and the dialog is cancelled, the next time the same dialog will be opened the fields will still be marked red although the illegal values are not present any more.	

Last modified on 2015-11-09T09:08:20+01:00