

## WEB-PLC V8.0.2 - Known Bugs

**Component: WEB-PLC - Editor** (13 matches)

Ticket	Summary	Description	Workaround
<b>#878</b>	Cycle time is calculated wrongly when removing an element	When removing an element and no time unit associated with time is present, the process time is decreased -300 more than expected. This leads to diagrams no loading properly.	When a diagram fails to load set a greater cycle time and save/reload it.
<b>#890</b>	OpenVPN and messages units can be inserted into the diagram although not supported on SC1x8	The OpenVPN and messages units can be added to the diagram although these features are not supported on SC1x8 processor based com.toms, yet. Storing a diagram with these units fails.	
<b>#936</b>	Units AND, OR, XOR must be bitwise operators	Units AND, OR, XOR must be bitwise operators like they were before the optional number of inputs was introduced.	
<b>#993</b>	Time Switch units should be processed in input stage	Currently Time Switch units are processed in the process stage of the IPO cycle. All other units that have only output ports are processed in the input stage so that their output ports have the latest values when the process stage starts.	
<b>#996</b>	Ports cannot be negated after ports have been added/deleted	After ports have been added and/or deleted to/from an element, some ports cannot be negated any more.	
<b>#1003</b>	Editor catches the delete key even if a dialog is open	The WEB-PLC editor catches the delete key and thus deletes the selected element even if a dialog is open and the key is pressed inside this dialog.	
<b>#1005</b>	Counter units overflow port only set for	The Overflow port of the counter unit is only set for one PLC cycle in case of an overflow. The documentation states that it will be set until the counter value changes the next time.	

	one cycle		
<b>#1034</b>	Diagram stopped after update with new I/O drivers	After the WEB-PLC has been updated to a new version that introduced new I/O drivers (Modbus Master in V4.11, CODESYS network variables in V5.04, Modbus Slave in V8.1.2), the diagram is stopped due to changes in the I/O configuration. The WEB-PLC should recognise that the new I/O configuration is a superset of the previous one and start the diagram.	The diagram must be converted, saved and started through the editor.
<b>#1041</b>	Diagram stopped after update with configurable variables	Since the variables are configurable, the WEB-PLC will not start diagrams created with previous versions (< V8.0.2), because it falsely detects a change in the variable configuration.	The diagram must be converted, saved and started through the editor.
<b>#1042</b>	Diagram stopped after update with configurable data type for Modbus Client/Master values	Diagrams that were created before the data type was configurable for Modbus Client/Master values (< V5.04, see <b>#171</b> ), will not be started, because the WEB-PLC will falsely detect a change in the I/O configuration.	The diagram must be converted, saved and started through the editor.
<b>#1063</b>	Diagram cannot be saved when edited with zoom	When the diagram has been edited while the zoom feature of the web browser was used, it may not be possible to save the diagram. The error message "JSON: This is a floating point number." will be shown. The problem has been observed in Microsoft Internet Explorer 11.	
<b>#1089</b>	Variables settings site grid fails to render fully if many Variables are configured.	If the grid has more than 30 Variables, adding a new Variable through the "add" or "clone" may lead to the new Variable not being visible.	The configured Variables are in the grid but are not displayed by clicking "ok". They are saved and by clicking "reload" the Grid will rerender and display them. If "ok" is not clicked, the "invisible" Variables will be lost by clicking "reload".
<b>#1316</b>	Modbus TCP Client: No more requests after Modbus exception	If the Modbus TCP Server returns a Modbus exception (e.g. illegal data address) on a request from the Client, the Client will not send any more requests to this during the current cycle. In the next cycle it will start with the very first request. If the Client for example tries to request an illegal data address, the Server will always return an exception and further requests will never be sent.	

Ticket	Summary	Description	Workaround
#708	Show OpenVPN information on portal even if connection cannot be controlled through portal	Information on the OpenVPN connection should be shown on the com.tom PORTAL even if controlling the OpenVPN connection through the portal is not allowed.	
#792	Floating point values are cut on home page	On the home page when floating point values from an I/O driver are displayed, the decimal places of these values are cut.	
#837	OpenVPN server with port number >32767 still does not work	<p>The OpenVPN does not work with servers that use a port number higher than 32767. The message "OpenVPN Driver: Options error: Bad port number: &lt;port number&gt;" is logged.</p> <p>This issue was already described in ticket #709, but the fix for this ticket was not effective.</p>	
#851	Ensure that each Event Log Message is transmitted to Portal	With the current implementation of the Portal Event Log there is a possibility that some events are never transmitted to the portal.	
#861	Time synchronisation with Kolibri Broker calculates round-trip time wrongly	When the current date and time is requested from the Kolibri Broker, the com.tom measures the round-trip time of the request in order to estimate the time that has passed since the Broker sampled the date and time. The round-trip time is multiplied with 1000 so that the clock will be fast.	
#870	Update does not work on SC1x8	On SC1x8 processor based com.toms updates stop in the programming stage.	
#871	Can't load daylight saving time rules on SC1x8	WEB-PLC can't find the daylight syving time rules on SC1x8 processor based com.toms.	
#872	Time switch units configuration file path missing on SC1x8	The TimeSwitchService uses the same path for SC1x3 and SC1x8 processor based com.toms.	
#887	SC1x8	com.tom devices that are based on the SC1x8 processor cannot be found or configured	

	com.tom cannot be found in IP tool when gateway is invalid	with the com.tom IP-Tool or the @CHIPTOOL if they do not have a valid gateway.	
<b>#904</b>	Daylight Saving Time rules are applied before System has its time configured	At startup the System Time Manager tries to load the Daylight saving time files before the device has a valid time which results in the warning: Timezone daylight saving time rules were depleted.	Once the device configures it clock the correct rules are loaded.
<b>#908</b>	Empty configuration packages are invalid	If you export the configuration of the WEB-PLC to a CUP file, but do not select any group of configurations, the generated CUP file is invalid.	
<b>#922</b>	No update package can be loaded after an invalid package had been loaded	When an invalid update package has been loaded to the WEB-PLC (either through the local website or through the portal) no further package can be loaded through the same channel afterwards.	Reboot the device.
<b>#929</b>	Update including RTOS does not work on SC1x8	On SC1x8 processor based com.toms updates that include an RTOS cannot be programmed.	
<b>#964</b>	I/O data type not updated on portal	If the data type of an existing I/O changes, the data type of the corresponding portal node is not updated.	Remove the I/O so that the corresponding portal node will be deleted and then re-create it with the new data type. The portal node will be re-created with the correct data type.
<b>#977</b>	Portal nodes of I/O arrays elements have a wrong description	If a value is an array its underlying values should have an empty description field, instead they use the device description field.	
<b>#984</b>	Interface for Ininet MicroBrowser treats Signed 16 bit values as Unsigned.	The com.tom library's interface for IniNet Solutions' MicroBrowser handles the Signed 16 bit values as Unsigned.	
<b>#1024</b>	Both RTC and	The system time manager always queries the RTC and SNTP servers when both are	

	SNTP are queried	available and enabled. However if the clock can be synchronised to an SNTP server, the RTC should not be queried before.	
#1025	Problems with 32 GB SDHC cards	The SDHC card driver has problems with 32 GB cards. The size is calculated wrongly, which may lead to access failures.	
#1030	Portal communication stops when a lot of data is pending	When a lot of data is pending to be transmitted to the portal, sending the data may fail and the connection to the portal will be closed. When the connection is re-established, the same will happen. Portal communication will be completely blocked.	Rebooting the device will probably help, if the pending data has summed up due to longer communication loss. Note that data will be lost in this case.
#1049	Daylight saving time rules switch times are wrong.	The Daylight saving time rules were wrongly calculated so the device changes 1 hour earlier the dst rule on and 2 hours later the dst rule off. That means that for the year 2016 with 'EU' dst rules the device should have added one hour on Sunday, 27. March 2016, 01:00:00 UTC but instead it does it at Sunday, 27. March 2016, 00:00:00 UTC, and it should remove one hour at Sunday, 30. October 2016, 01:00:00 UTC but instead it does it at Sunday, 30. October 2016, 02:00:00 UTC.	
#1060	Messages cannot be sent and received after a restart	Messages generally only work when the diagram has just been saved and started. After the device has been restarted, messages cease to work.	
#1067	Cannot receive short messages from self	The WEB-PLC cannot receive short messages that it has sent itself. These messages may also block other messages. This problem may be limited to certain networks.	
#1068	Cannot receive multi-line short messages	The WEB-PLC cannot process received multi-line short messages. There are two special cases: If the second line contains only the word OK or the second line is empty and the third line contains only the word OK, only the first line will be processed.	
#1079	Portal: Drivers with Boolean Values trigger node creation or modification errors.	A Boolean Value Portal Node can't have the ScalingFactor or ScalingOffset properties. Currently the I/O Portal synchronisation module does not check the dataType of the node to be created and may cause a "Could not create node." or a "Could not modify node" error.	
#1189	Update package and log file deleted on error	The update launcher deletes the log file and the update package file in case of an error during installation of the update package. The log file should not be deleted. The update package should not be deleted, if the update was triggered through the com.tom's reset button.	
#1191	Multiple instances of the same TimeSwitch do not work	If a diagram uses multiple instances of the same Time Switch Unit (for example "TestSwitch1") only the first one will trigger accordingly to the predefined schedule, all other Units will always output "0".	Use only one instance of each TimeSwitch in the diagram.

#1215	Portal: No valid point state for points with trigger mode 5 (domain trigger)	If a data point has the domain trigger mode (5) configured on the portal, the WEB-PLC will transmit a zero value (quality invalid, timestamp 1970-01-01 00:00:00) to the portal when the corresponding domain triggers.	
#1389	SNTP client hangs on receive timeout on SC1x8 based com.toms	On SC1x8 processor based com.toms the SNTP client will hang forever - and thus never update the system time - if receiving a reply from an NTP server times out once.	
#1402	IEC 60870-5-104 Server: "Transmission cause false" after Counter interrogation command	If the IEC 60870-5-104 Server has the types "15 Integrated Totals" and "37 Integrated totals with time tag" and receives a "101 = Counter interrogation command" with "Qualifier of interrogation" = 5 (General counter interrogation), it answers with Cause of transmission 0. Additionally the type 37 is transmitted as type 15.	

**Component: WEB-PLC - Run Time System** (16 matches)

Ticket	Summary	Description	Workaround
#830	Deactivate SNTP client in IEC 61850 driver	The IEC 61850 driver should not implement another SNTP client.	
#855	NBTNS does not work	The com.tom's hostname cannot be resolved through NBTNS any more.	
#889	IEC 60870-5-104: Four years added to time tags before 2000-01-01T00:00:00	If a value is transmitted with a time tag before 2000-01-01T00:00:00, four years are added to the time tag.	
#906	Too many Event Log messages about a failing supervision URL	There are too many Event Log messages about a failing supervision URL.	

	URL		
<b>#913</b>	Messages: I/O or variable value may be cut at end of message	When messages become too long, they will be cut. However they should not be cut in a way that I/O or variable values are included partly. This could lead to confusion. If the message becomes too long, it must be cut before any value that does not fit.	
<b>#1046</b>	IEC 61850: Client only reads one item from server on each polling cycle	In the client role enabling the "Poll data from servers" check box should read all readable items on connected servers but only one item is read on each cycle.	
<b>#1054</b>	Unknown quality and timestamp 0 on portal for CODESYS network variable inputs	When input values from the CODESYS network variable driver are transmitted to the portal, the quality will be unknown and the timestamp will be zero if the corresponding CODESYS network variables list is not transmitted with checksum.	
<b>#1059</b>	IEC 60870-5-104 server driver: Wrong assignment of portal qualities	The IEC 60870-5-104 server driver does not update the quality of the data points for its input values on the portal. Instead it writes the corresponding qualities to the points for its output value.	
<b>#1076</b>	CODESYS network variable handles DINT dataType as signed long.	The CODESYS network variable DINT dataType is defined as unsigned long, but the driver handles it incorrectly as a signed long.	
<b>#1083</b>	Modbus Server/Slave input qualities and timestamps invalid	Modbus Server/Slave input values that are written by the Client/Master as Coils may have invalid qualities and timestamps.	
<b>#1102</b>	Modbus: 64-bit floating point values may be set to 0	When transmitting 64-bit floating point values as registers through the Modbus Client/Master or Server/Slave driver, the values might be set to 0.	
<b>#1183</b>	Teridian E-Meter driver: Power Factor	The Teridian E Meter driver interprets the Power Factor values (L1, L2, L3 and sum) as unsigned values although they are in fact signed values.	

	interpreted as unsigned	
<b>#1202</b>	Retentive variables not invalidated on configuration change	When the configuration of the variables changes, the retained values of retentive variables are not invalidated. All retentive variables should be set to zero.
<b>#1208</b>	Modbus Client: Qualities and timestamps shifted if not connected to server	If the Modbus TCP client loses the connection to a certain server, the input qualities and timestamps of subsequent servers are assigned to the values of this server, shifting the qualities and timestamps of all following servers. If there is for example one server with two input values and another one with four input values and the connection to the first server is lost, the qualities and timestamps of the first two values of the second server will be assigned to the values of the first server, the qualities and timestamps of the last two values of the second server will be assigned to the first two values of the second server and the qualities and timestamps of the last two values of the second server will not be updated at all.
<b>#1289</b>	Digital outputs on com.tom M-BUS cannot switch faster than once every second	The digital outputs of com.tom M-BUS devices (EXT03) cannot switch faster than once every second. If you try to switch them faster than this, they will not switch at all. If you try to switch them only slightly slower they may switch or not.
<b>#1320</b>	Cannot handle certain old Modbus configurations	The Modbus Master/Client driver cannot handle certain configurations from before version 5.04. It is necessary to convert and start the diagram. Back then the data type of a value could not be configured. The current Modbus driver can only handle these old configurations if the implicit data type of all values is 32-bit signed integer.

### Component: WEB-PLC - Settings Website (32 matches)

Ticket	Summary	Description	Workaround
<b>#422</b>	OpenVPN file upload shows no error when no file has been selected	The OpenVPN certificate file upload dialog shows a success message when no file has been selected for upload.	
<b>#425</b>	Duplicate MAC and IP addresses not checked in DHCP server settings	The DHCP server settings form does not check that no IP or MAC address is used twice.	
<b>#427</b>	Duplicate ports	The NAT settings form does not check that no external port is used twice.	



	not checked in NAT settings		
<b>#510</b>	Gateway only valid for Ethernet (0) interface	The gateway IP address that can be configured through the network settings form is only valid for the Ethernet (0) interface.	
<b>#826</b>	IEC 61850 configuration form may store inconsistent configuration	The configuration form of the IEC 61850 interface may store an inconsistent configuration. If the upload of the SCL file fails, the interface will not show an error message and still store other parts of the configuration. The inconsistent configuration will prevent the IEC 61850 driver to start.	
<b>#873</b>	Nat and Firewall missing Network interface Wlan.	The wlan NetWork interface is missing from nat and firewall it must be activated in the website when wlan is enabled.	
<b>#898</b>	Clear button in TimeSwitches Webconfig does not properly restore name.	When the clear button in used in TimeSwitches Webconfig, instead of setting the name as TimeSwitch1, TimeSwitch2, etc it renames them to TimeSwitchundefined.	
<b>#902</b>	TimeSwitches Webconfig causes a json parsing error with Trigger type as List	if list is selected as trigger type and the trigger has less than 5 values a json parsing error happens in the booting sequence of the WEB-PLC.	Triggers using Lists should always have 5 values, duplicate values do not trigger the TimeSwitch twice.
<b>#905</b>	Messages: Umlauts in message text lead to a 500 server error	Umlauts in message text lead to a 500 server error, after clicking the OK button.	
<b>#909</b>	Portal: Several event log messages not correctly linked to help	The following event log messages considering the portal communication are not correctly linked to the help: <ul style="list-style-type: none"> <li>• Invalid sequence number &lt;sequence number&gt;</li> <li>• Write/commit command timeout for point &lt;path&gt;</li> <li>• Could not process get node properties response: Invalid frame length</li> <li>• Could not execute kolibri.getStats() RPC: Error getting statistics (&lt;error code&gt;)</li> </ul>	
<b>#910</b>	ComServer configuration visible on	On com.toms based on the SC1x8 processor the configuration form for the ComServer is visible on the settings website although this feature is not available on SC1x8 based com.toms, yet.	

	SC1x8 although not available		
<b>#911</b>	Login Tab: Validation of form does not show all errors or too many errors	When entering wrong values in the Login Tab, not all errors are marked after clicking OK.	
<b>#912</b>	OpenVPN status shown on SC1x8 although not available	On com.toms based on the SC1x8 processor the status of the OpenVPN is shown on the home page although this feature is not available on SC1x8 based com.toms, yet.	
<b>#914</b>	Portal configuration allows to disable keep-alive although this is not possible	The configuration form for the portal settings accepts the value 0 for the <i>keep-alive interval</i> , which means that the keep-alive mechanism would be disabled. However, disabling the keep-alive mechanism is not possible. If the value 0 is entered and the device is rebooted, it will not start correctly, but show the error message "Run Time System: Fatal error: Portal module: Could not set keep alive options. (16)".	
<b>#928</b>	No progress indication during file upload on SC1x8	On com.toms based on the SC1x8 processor no progress is indicated while uploading files through the local website.	
<b>#935</b>	Profinet device name suffix must not start with a hyphen	The Profinet device name suffix must not start with a hyphen. The prefix already ends with a hyphen and two consecutive hyphens are not allowed. Of course the suffix itself must also not contain two consecutive hyphens.	
<b>#1031</b>	Memory leak on SC1x8	The firmware has a memory leak on com.toms based on the SC1x8 processor. Memory will be used up while a password-protected website is open.	
<b>#1032</b>	Upload of update package fails on SC1x8	On com.toms based on the SC1x8 processor, the upload of update packages fails, if the device has never been rebooted.	Reboot the device once
<b>#1033</b>	Problem with website password protection and file upload on SC1x8	On com.toms based on the SC1x8 processor, problems with password protected websites may occur. The password may be considered wrong although it is correct. In combination with the upload of update packages even the password dialog may be suppressed and the upload will just timeout.	Renaming the update package may help.
<b>#1045</b>	IEC61850: Table with process items	When uploading a server SCL file the table with process items may not reflect the selected signals in the SCL file.	

	occasionally out of sync with tree view selection after uploading server SCL file		
<b>#1053</b>	Dialogs have fields marked erroneous initially	When input fields in a dialog are marked red due to illegal input values and the dialog is cancelled, the next time the same dialog will be opened the fields will still be marked red although the illegal values are not present any more.	
<b>#1088</b>	Variables Settings Site does not display all error messages.	While "add" and "clone" buttons do not allow the configuration of more than 64 Variables, if the user tries to add more Variables, an error is generated but no message is displayed.	
<b>#1104</b>	Modbus Client/Master: 64 devices can be configured but only 32 are allowed	The configuration form of the Modbus Client/Master driver allows to configure 64 devices although only 32 are allowed. Storing the configuration will fails.	
<b>#1282</b>	I/O references should be ignored in receive message templates	It is not possible to add I/O references to receive messages templates through the menu. However it is possible to manually write a reference to the template. This reference should be ignored. It should be treated as plain text. Instead the reference is evaluated and inputs and outputs can be directly modified through receive messages.	
<b>#1294</b>	Modbus Master: Check of maximum values on edit value	The check of the maximum allowed values including scalar and array values does not show an error message, when a value is edited and it does not change from input to output or vice versa.	
<b>#1300</b>	Modbus Slave: Cannot save RTU settings if TCP settings are wrong	Cannot save RTU settings if TCP settings are wrong, although these settings are mutually exclusive.	
<b>#1313</b>	PROFINET IO Device: Default device address should be 1	For PROFINET IO Device the default device address is 0, although this is not a valid device address. It should be changed to 1.	
<b>#1327</b>	Cannot send	It is not possible to include a percentage sign in a send message template, because it	

	percentage sign in messages	is interpreted as the start of a reference.	
#1344	IEC 60870-5-104 Server: Edit value does not recalculate sum of array elements	The Edit value dialog does not recalculate sum of array elements. If the maximum is reached by adding values and then one value is edited and the range (array elements) is reduced, it is still not possible to add new values.	
#1347	IEC 60870-5-104 Server/Client: Duplicate names are allowed	IEC 60870-5-104 Server/Client settings website should not allow Duplicate names.	
#1348	Help does not work when other site opened in help window	When the help button is clicked on the WEB-PLC's website, a new window/tab is opened for the online help website. If one of the other websites is opened in this window/tab, the help button will not work anymore.	
#1396	CODESYS Network Variables: Missing comma after the name of the list	There is a comma missing after the name of the list, if the list has a name. The "Unnamed list" has a comma.	

**Component: com.tom Library** (1 match)

Ticket	Summary	Description	Workaround
#894	Input values on com.tom METER 2.1 assigned wrongly	The values of inputs "Meter Values.Voltage (2)" and "Meter Values.Power factor (2)" are invalid.	